From The Chief Engineer, M.I 3rd Floor, Jalasoudha, Eruum Manzil, Hyderabad - 82

The Superintending Engineer

Lr.No.:CE/MI/DCE/APCBTMP - TU/09/GenI-

Dt.2612.09.

Sir.

Sub:- APCBTMP - Quality Control Sub division - Redistribution of works -Instructions - issued - reg.

The Minor Irrigation works are hitherto looked after by different sub - divisions particularly in respect of APCBTMP works, the Deputy Executive Engineers are reporting to District Project Director and in turn to Superintending Engineer,/ Irrigation circle. As per the QC manual, entrust (copy enclosed) one sub division shall look after QC operations and the Deputy Executive Engineer shall report to Superintending Engineer concerned.

In as much as number of works are grounded and it is targeted to ground 1500 works by 03/2010 the role of QC Deputy Executive Engineer with supporting staff is very very important. Hence in order to have effective Quality Control and Quality Asurance it is necessary that the Deputy Executive Engineers along with senior officers shall have to bestow their efforts on QC only and also an exclusive laboratory is already set up and furnishing in the district.

in this content it is highly necessary to delink construction/execution activities in QC sub divisions. The designated QC DEE must hold full charge and he should not be given additional charges of any other works/ Sub division. Also the Superintending Engineers are here by requested to redistribute the works among after sub divisions and report compliance.

Further Superintending Engineers are requested to furnish the location of office addresses of QC sub divisions along with names and phone numbers of QC DEEs/ AEE's . / AE's immediately. Encl:- Organogram

Chief Engineer

Copy to All the DPDs of the APCBTMP for information and necessary action. Copy to the State Project Director, APCBTMP, Hyderabad for favour of Information

Deputy Executive Engineer